



INOGENI CAMTRACK Firmware Release Notes

RELEASE HISTORY

Here is the history of the CAMTRACK releases:

Release	Description
3.6.0 – 2026-05-07	<p>New features:</p> <ul style="list-style-type: none">• AutoTrack support for Canon CR-N series cameras using the Canon RA-AT001 Auto-Tracking Application.<ul style="list-style-type: none">◦ (on/off with Light license, full parameter control with Full RA-AT001 license)• AutoTrack control added to Channel Table.• Support for Inogeni IP2USB.• Supported switchers with the CAMTRACK PRO version:<ul style="list-style-type: none">◦ Crestron DM-NVX.◦ Blackmagic Design Videohub 12G Series and ATEM Mini/Constellation.◦ Roland HD Switchers.◦ Extron switchers.◦ Please see detailed model list in the user guide.• Caller status synchronization for INTELLIMIX® P300, INTELLIMIX® ROOM SOFTWARE, ANIUSB-MATRIX (On hook / Off hook).• NDI configuration with Group Name and Discovery Server. <p>Improvements:</p> <ul style="list-style-type: none">• Reduced minimum time between camera/preset recalls from 2.5s to 1.5s.• Improved hostname and mDNS handling.• Improved switcher input configuration by showing connected output device descriptions.• Updated dashboard layout and grouping. <p>Bug Fixes:</p> <ul style="list-style-type: none">• Fixed switcher output handling (now dynamic).• Added support for Sony Digest Authentication.
	<p>Official release.</p>
3.4.0 – 2025-12-15	<p>Improvements:</p> <ul style="list-style-type: none">• In the Zone Editor, CAM A/B/C have been replaced by VIEW A/B/C to eliminate confusion.• Zone dragging/resizing in the Zone Editor has been refined to make selection easier. Directly clicking on the ID is no longer required.• Adding grid to Zone Editor.• Imperial measures handling in the Zone Editor has been implemented.• Priority on "No Microphone Active" and "2 or More" channels. The stars are no longer selectable, which is also reflected by the mouse pointer.• The Zone Editor is now shown by default during initial setup and can, if not desired, be hidden using the switch <p>Bug Fixes:</p> <ul style="list-style-type: none">• Corrected global preset recall issue.

KNOWN ISSUES

Here are the known issues for this specific product. These will be corrected throughout the firmware releases.

- The SET CHANNEL AUDIO API command needs a third value set to 0 and it is not documented as it is supposed to only use 2 values
 - Value1="channel number"

- Value2="Enable or Disable
- Value3=0
- Here is the work around:
 - <http://<ipaddress>>:1881/control?command=SET%20CHANNEL_ID_AUDIO&value1=101&value2=ENABLE&value3=0